


2" THREE-WAY TEE



4" & 6" THREE-WAY TEE

MATERIAL LIST

QTY	DESCRIPTION	STOCK NO.	QTY	DESCRIPTION	STOCK NO.
1	STEEL GAS MAIN		4	TRANSITION FITTING	
2	THREE WAY TEE		1	2"	203145
	SIZE:			4"	203155
	2"	205322		6" SDR 11.5	203156
	4"	205334		6" SDR 21	203157
	6"	202508	5	PROTECTIVE SLEEVE (INCLUDED IN TRANSITION PACK)	
3	WELD X WELD FULL-OPENING GATE VALVE		6	VALVE BOX PER GS-170	
	2"	204446	7	17 LB ANODE	202015
	4"	204453			
	6"	204460			

<div>△</div>		<i>GENERAL NOTES</i>		<i>CONSTRUCTION STANDARD CITY UTILITIES OF SPRINGFIELD, MISSOURI</i>	
1	GATE VALVE TO BE IN CLOSED POSITION DURING WELDING.			<i>SIDE TAP OFF OF STEEL MAIN USING 3-WAY TEE STEEL VALVES</i>	
2	IF SOCKET FUSION IS USED, PROTECTIVE SLEEVE MAY BE TRIMMED AS NECESSARY.				
3	IF CONNECTING TO STEEL TRANSITION FITTING NOT TO BE INCLUDED.				
4	RUN TRACER WIRE INSIDE VALVE BOX; TAPE NEAR THE TOP.				
5	APPLY GLASS MESH AND MASTIC. ALLOW MASTIC TO DRY FULLY BEFORE BACKFILLING.				
6	COMPACT FILL UNDER VALVE OR BLOCK USING FILLED SAND BAGS.				
		LATEST REV. DATE	STANDARD NO.	PAGE:	
		01/24/2003	GS-117		