


SO - CONN



MATERIAL LIST

QTY.	DESCRIPTION	STOCK NO.	QTY.	DESCRIPTION	STOCK NO.
1. AS REQD	1/0 ALUMINUM QUADRAPLEX SERVICE WIRE.	101123			
2. AS REQD	4/0 ALUMINUM QUADRAPLEX SERVICE WIRE.	101132			

- GENERAL NOTES**
- USE THE INSULATED CONDUCTOR WITH ONE RAISED RIB AS THE WILD LEG WHEN RIBS ARE PRESENT.
 - WHEN NO RIBS EXIST USE COLORED TAPE TO IDENTIFY THE PHASES AS FOLLOWS: ORANGE FOR THE WILD LEG AND RED AND BLUE FOR THE OTHER PHASES.
 - THE WILD LEG IS THE PHASE CONDUCTOR WITH VOLTAGE OF 208 VOLTS TO NEUTRAL.

**ELECTRIC SERVICE STANDARD
CITY UTILITIES OF SPRINGFIELD MO.**

DRAWN BY: D.H.	SERVICE OVERHEAD QUADRAPLEX SERVICE CONNECTIONS		
REV BY: W.BROOKS			
FILE: SO-CONN			
APPROVED: 06/05/06	REVISED: 07/16/02	SHEET OF 1 OF 1	STD. NO. SO - CONN