

MATERIAL LIST									
	QTY	DESCRIPTION	<i>STOCK NO</i>		QTY	DESCRIPTION	<i>этоск но.</i>		
1		STEEL GAS MAIN		4	1	TRANSITION FITTING	007445		
2	1	THREE WAY TEE SIZE: 2" 4"	205322			2" 4"	203145 203155		
		<i>4</i> "	205334	5	1	PROTECTIVE SLEEVE (INCLUDED IN TRANSITION PACK)			
3	1	POLYETHYLENE VALVE 2" 4"	204466 204485	6	1	17 LB ANODE	202015		

GENERAL NOTES

- 1 4" MAY USE EITHER BUTT FUSION OR COUPLINGS.
- 2 2" IS TO USE COUPLINGS ONLY, 6" IS TO USE ELECTROFUSION COUPLINGS ONLY, PROTECTIVE SLEEVE MAY BE TRIMMED AS NECESSARY.
- 3 IF CONNECTING TO STEEL WELD VALVE SHOULD BE USED. OMIT TRANSITION FITTING.
- 4 RUN TRACER WIRE INSIDE VALVE BOX; TAPE NEAR THE TOP.
 - APPLY GLASS MESH AND MASTIC. ALLOW MASTIC TO DRY FULLY BEFORE BACKFILLING.
 - UNDER VALVE USE SAND BAGS OR WOOD BLOCKING.

5

6

CONSTRUCTION STANDARD
CITY UTILITIES
OF SPRINGFIELD, MISSOURI

SIDE TAP OFF OF STEEL MAIN USING 3-WAY TEE PLASTIC VALVE

LATEST REV. DATE	STANDARD NO.	PAGE:
05/21/2001	CC_118	1
03/21/2001	63-110	1